Internal File

2005 Annual Report Review

9K
0.

Permittee:	Andalex Resources, Inc.	
Mine Name:	Wildcat Loadout	
Permit Number:	C/007/033	
Date Report Received:	March 31, 2006 @ Price DOGM	
Assigned Reviewers:	Peter Hess, Engineer / Inspector	Date Completed τ
_	Jim Smith, Hydrology 25 03/05/06	04/27/2007
	Jerrianne Ernstsen Biology	2/26/08
_		

<u>Instructions:</u> The assigned staff will review their respective portions of the Annual report and provide a written determination (findings) on how the mine has or has not met the permit requirements for reporting. If the report is deficient or remedial action is required to obtain compliance, this should be noted and the inspector notified. Once all reviewers have completed the report, they should initial it and a copy will be filed in the Mine Internal File.

Assignments:

Inspectors:

Review each cover sheet, AVS Legal/Financial, Mine Sequence Maps.

Hydrologists:

Review Water Monitoring Data, Precipitation and Climatological Data, Non-Coal Waste

Biologists:

Review Vegetation/Revegetation Success Monitoring, Raptor Survey

Engineers:

Review Subsidence Monitoring Data, Annual Impoundment Certification, Annual Overburden,

Spoils, Refuse, Floor, etc.

SECTIONS TO REVIEW	SUBMITTED YES NO		FINDINGS	
Cover Sheet			The submitted cover sheets appear to provide adequate and complete information.	
AVS; Legal/ Financial Update			Cover sheet Page 3 indicates that the Permittee has filed an Annual Report of Officers with the Utah Dept. of Commerce; this same information is on file with the DOGM.	
Mine Sequence Map			No site maps have been submitted to the DOGM as part of this annual report for 2005. This facility is a storage/blending/shipping facility and does not conduct underground coal extraction activities. The submittal of maps required under R645-301-525.240 which are relative to subsidence monitoring is not relative.	
Water Monitoring Data			Submitted electronically each quarter via the UDOGM website.	
Precipitation & Climatological Data			N/A - No reports are required.	
Non-Coal Waste report			N/A - No reports are required. Non-coal waste is not disposed of on-site.	
Subsidence Monitoring Data			This is a surface operation only. Coal extraction from a natural deposit is not conducted. The requirements of R645-301-525 are not applicable.	

2005 Annual Report Review

SECTIONS TO REVIEW	SUBMITTED YES NO		FINDINGS
Annual Impoundment Certification			Appendix A of the 2005 Annual Report contains the fourth quarter 2005 and annual impoundment inspections/certifications (conducted 10/25/2006) for ponds A through F, as well as the permanent impoundment and the depression area. There were no hazardous conditions noted; several ponds were reported as being low on remaining sediment storage capacity. This was corrected by the Permittee during the spring of 2006. Mr. Dan Guy, P.E., is the Permittee's qualified inspector.
Annual Overburden, Spoil, Refuse, Floor, etc.			Appendix A of the 2005 Annual Report contains the four quarterly inspection reports/P.E. certifications required for the waste rock disposal site. Mr. Dan Guy, P.E., conducted these inspections/certifications. There were no hazardous conditions reported. The permittee places coal mine waste, concrete material, and pond cleanout material here for final disposal.
Vegetation Data		х	Not required or submitted as indicated in Annual Report 2005 cover sheet.
Revegetation Success Monitoring		x.	Not required or submitted as indicated in Annual Report 2005 cover sheet
Raptor Survey		x_	Not required or submitted as indicated in Annual Report 2005 cover sheet
Other Information			